



SOLAX
POWER

Notice

Please update inverter to latest firmware version to make it compatible with Wireless Bridge.

The USB disks in the WB box have the required firmware files stored on them for X1-Hybrid/Fit-G4 and X3-Hybrid/Fit-G4 models. Please refer to the “Firmware upgrading” section [from contents page] in your inverter’s user manual. (Please plug the disk into “upgrade port”)

Alternatively, scan the below QR code for an instruction video.



For any other models, please contact our global call center (+448081686588) after connecting the inverter to the SolaxCloud. If you cannot connect the inverter to the cloud, please contact service.uk@solaxpower.com and we will provide the appropriate USB